

APPENDIX D: SITE PHOTOGRAPHS



Figure 1: Aerial Image of the proposed dam, pipeline and location of the weir



Photo 1 was taken from NNW to SSW indicating cultivated land on which the dam is proposed



Photo 2 was taken from NNW to SWS still indicating cultivated land on which the dam is proposed



Photo 3 was taken from the centre of the site showing the seasonal stream, facing SE



Photo 4 was taken from the centre of the site showing the seasonal stream, facing NW



Photo 5 was taken from W to E indicating cultivated land on which the dam is proposed



Photo 6 was taken from W to NE indicating cultivated land on which the dam is proposed



Photo 7 indicating the path of the seasonal stream to the NW



Photo 8 indicating the path of the seasonal stream to the SE



Photo 9 indicating where the dam wall is proposed to the NW



Photo 10 indicating where the dam wall is proposed to the S



Photo 11 indicating where the dam wall is proposed to the SE



Photo 12 indicating where the dam wall is proposed to the W



Photo 13 indicating where the dam wall is proposed to the N



Photo 14 shows the way to Eksteenskloof weir



Figure 15 indicating the broken weir



Figure 16: indicating the broken weir



Figure 17: Photo from Botanical specialist (Peet Botes) indicating disturbed areas on the eastern banks of the stream where the rehab of the weir is proposed which can be used for the parking/ working area near the weir.



Figure 18: Photo from Botanical specialist (Peet Botes) showing agricultural/ disturbed land to the east of the stream where the rehab of the weir is proposed.