

Photo 7: Taken from point 3, looking north-east up the dirt road through Rem Farm 70.



Photo 9: Taken from point 5, looking north-west over the site.



Photo 11: Taken from point 6, looking south-west. The degraded nature of the site and illegal waste dumping is evident closer to the boundary of the site.



Photo 12: Taken from point 6, looking south-east. The degraded nature of the site and illegal waste dumping is evident closer to the boundary of the site.





Photo 8: Taken from point 4, at the existing livestock pens to the north of the site.



Photo 10: Taken from point 5, looking south over the site.

Photo 13: Taken from point 7, looking north-west. The site (Erf 15089 can be seen to the right of the image, and the existing informal residences to the left.



Photo 9: Taken from point 7, looking west at the existing informal residences on Erf 15089.



Photo 11: Taken from point 8, looking west. The site (Rem. Farm 70) can be seen to the right of the image. The area is currently used as an informal sports field.



Photo 8: Taken from point 7, looking north -east over the site. The illegal dumping of waste is once again evident in this image.



Photo 10: Taken from point 7, looking north-east at the wet area on Erf 15089, as a result of leaking pipes.



Photo 12: Taken from point 8, looking north over the site. Once again illegal waste dumping is evident on the site.



Google Earth image of the photograph positions.

