

SITE PHOTOGRAPHS: PROPOSED 30M HIGH TELECOMMUNICATION MAST ON PORTION 14 OF THE FARM HEMEL EN AARDE NO. 587, HERMANUS, WESTERN CAPE - 13 FEBRUARY 2019



Figure 1: A view of the site (red arrow), looking north toward the property fence. Several tall bluegum trees are located to the south of the site. Looking in a southern direction. The site is located in the south-western corner of the property.



Figure 2: A view of the proposed site (red arrow), looking in a south-eastern direction. The site is completely transformed and degraded with no natural vegetation present.



Figure 3: A view of the proposed (red arrow), looking in an eastern direction. The site is completely transformed and degraded with no natural vegetation present.



Figure 4: A view of the proposed site (red arrow), looking in a northern direction towards Ertjiesvlei hall, which are used a church. The site is completely transformed and degraded with no natural vegetation present. An outside toilet approximately 10m north of the site.




Figure 5: A view of the proposed site, looking in a north-western direction towards Ertjiesvlei hall and Hemel en Aarde Road. An old toilet located approximately 10m south of the site. The site is completely transformed with no natural vegetation present.



Figure 6: A view of the proposed site (red arrow), looking in a north-western direction towards Hemel en Aarde Road. The property to the west of the site is covered with a several tall bluegum trees.



Figure 7: A view of the area to the south of the site, looking in a southern direction.



Figure 8: A view of the proposed site (red arrow), looking in a southern direction. The site is located in the south-western corner of the property. The area immediately south and west of the proposed site is covered with large amounts of tall bluegum trees.



Figure 9: A view of the proposed site (red arrow), looking in a south-western direction. The site has no vegetation cover and is completely transformed and degraded. A toilet approximately 10m north of the site. The area immediately south and west of the site has tall bluegum trees. The area to the north-east of the site is covered with kikuyu grass (lawn).




Figure 10: A view of the access road and access gate as viewed from the south-eastern corner of the property. Looking towards Ertjiesvlei hall and Hemel en Aarde Road, looking in a north-western direction.



Figure 11: A view of the proposed site (red arrow), looking in a southern direction. The site is located on the south-western corner of the property.



Figure 12: A view of the proposed site (red arrow), looking in a north-eastern direction. The site is surrounded by some tall bluegum trees to the south and west.




Figure 13: A view of the proposed site (red arrow), looking in a northern direction towards Ertjiesvlei hall and Hemel en Aarde Road.




Figure 14: A view of the proposed site (red arrow), looking in a northern direction towards Ertjiesvlei hall on the property.



Figure 15: A view of the proposed site (red arrow), looking in a southern direction. The site is covered with some garden refuse and has no natural vegetation cover present. The area immediately south and west of the proposed site is covered with some tall bluegum trees.



Figure 16: A view of the proposed site (red arrow), as viewed from the outside toilet on the property; looking in a southern direction towards the site. The area immediately south and west of the proposed site is covered with some tall bluegum trees.




Figure 17: A view of the proposed site access road, looking in a north-western direction towards Hemel en Aarde Road.



Figure 18: The site (red arrow) is situated in the south-western corner of the property. Looking towards Ertjiesvlei hall which are being used as a church and for community purposes. Looking in a southern direction towards the site.