

Photo 1: Newly constructed thatched roof at the Property entrance (taken from position 1)



Photo 2: Newly constructed thatched roof at the Property entrance (taken from position 1)



Photo 3: Construction of the Main area/restaurant (taken from position 2)



Photo 4: Entrance road and completed units (taken from position 2)



Photo 5: Conservancy tank near completed units (taken from position 2)



Photo 6: Swimming Pool (taken from position 3)



Photo 7: Ablution facility with conservancy tank (taken at location 4)



Photo 8: Small drainage line running through the site. Ablution facility conservancy tank can be seen in foreground (taken from position 5)



Photo 9: General camp ground (taken from position 6)



Photo 10: General camp ground (taken from position 6)



Photo 11: Main area and some accommodation units under construction (taken from location 7)



Photo 12: Main area and some accommodation units under construction (taken from location 7)



Photo 13: Main area and some accommodation units under construction (taken from location 7)



Photo 14: Thatched gazebo constructed on river bank (taken from location 8)



Photo 15: Road constructed within drainage line (taken from position 9, looking south)



Image 1: Google Earth image of the photograph positions (positions 1 – 7)



Image 2: Google Earth image of the photograph positions (positions 8 – 9)



Image 3: Google Earth image of the Image positions (as per Google Earth Images 1 – 3 above)

