



Photo 1: A view of the informal dwellings on site. The site comprises of informal dwellings with access roads.



Photo 2: A view of the informal dwellings on site. The site comprises of informal dwellings with access roads.



Photo 3: A view of the informal dwellings on site; looking in a south-eastern direction. The site is transformed.



Photo 4: A view of the informal dwellings on site; looking in a southern direction. The site is transformed.



Photo 5: A view of the informal dwellings on site. The site is transformed.



Photo 6: A view of the informal dwellings on site. The site is transformed.



Photo 7: A view of the informal dwellings on site. The site is transformed.



Photo 8: A view of the informal dwellings on site, looking in a south-eastern direction. The site is transformed.



Photo 9: A view of the informal dwellings on site, looking in a south-eastern direction. The site is transformed.



Photo 10: A view of the informal dwellings on site. The site is transformed.



Photo 11: A view of the informal dwellings on site, looking in a south-eastern direction. The site is transformed.



Photo 12: A view of the informal dwellings on site, looking in a south-western direction. The site is transformed.



Photo 13: A view of the informal dwellings on site, looking in a southern direction. The site is transformed.



Photo 14: A view of the informal dwellings on site, looking in a southern direction. The site is transformed.



Photo 15: A view of the informal dwellings on site, looking in a southern direction.



Photo 16: A view of the informal dwellings on site. An A2 Poster was placed against the fence of a property on site.



Photo 17: A view of the informal dwellings on site. The site has access roads. Water is obtained through a JoJo tank on site.



Photo 18: A view of the informal dwellings on site. The site has dirt access roads.



Photo 19: A view of the informal dwellings on site. The site is transformed.



Photo 20: A view of the informal dwellings on site, looking in a north-eastern direction. The site is transformed and degraded.



Photo 21: A view of the site as viewed from the access road at M.J. Minimark; looking in a western direction.



Photo 22: A view of the site as viewed from the access road at M.J. Minimark; looking in a north-western direction.



Photo 23: A view of the site as viewed from the access road, looking in a north-western direction.



Photo 24: A view of the site as viewed from the access road, looking in a north-western direction.