

Appendix 3 - Site Photos



Appendix 3 - Site Photos



*Figure 1: Photo taken standing in the proximity of the dam toe locality, facing North towards the locality of the dam wall.
The drainage line visible in the photo*



Figure 2: Photo taken facing NNE

Appendix 3 - Site Photos



Figure 3: Photo taken facing NE



Figure 4: Photo taken facing East

Appendix 3 - Site Photos



Figure 5: Photo taken facing SE



Figure 6: Photo taken facing South. Drainage line visible

Appendix 3 - Site Photos



Figure 7: Photo taken facing SSW



Figure 8: Photo taken facing SW

Appendix 3 - Site Photos



Figure 9: Photo taken facing West



Figure 10: Photo taken facing WSW

Appendix 3 - Site Photos



Figure 11: Photo taken facing NW



Figure 12: Photo taken facing NNW