

Photo 1: Taken from point 1, looking south-east over the site



Photo 2: Taken from point 1, looking south-west over the site



Photo 3: Taken from point 1, looking west over the site. Notice extensive dumping on the site.



Photo 4: Taken from point 1, looking north-west over the site. Notice extensive dumping on the site.



Photo 5: Taken from point 2. The extensive dumping on this part of the site is clearly visible.



Photo 6: Taken from point 2. The extensive dumping on this part of the site is clearly visible.



Photo 7: Taken from point 3, looking east over the site.



Photo 8: Taken from point 3, looking south-east over the site.



Photo 9: Taken from point 3, looking south over the site.



Photo 10: Taken from point 3, looking south-west over the site



Photo 11: Taken from point 4, looking west. The raw sewage flowing in an open trench is visible in this image.



Photo 12: Taken from point 5, where the raw sewage is overflowing from the trench onto the open ground. This flow is clearly visible from the Google Earth image



Photo 13: Taken from point 6, looking north towards the site



Photo 14: Taken from point 6, looking north towards the site



Photo 15: Taken from point 7, looking north-east. The existing abattoir is located to the left of the image, and the site to the right



Photo 16: Taken from point 7, looking east over the site



Photo 17: Taken from point 8, looking north-east over the site



Photo 18: Taken from point 8, looking south-east over the site



Photo 19: Taken from point 8, looking south over the site



Photo 20: Taken from point 8, looking south-west over the site



Photo 21: Taken from point 8, looking west over the site



Photo 22: Taken from point 8, looking north-west over the site



Google Earth image of the photograph positions. Photographs taken on 19 May 2020

