

Appendix C: Site Photographs Driefontein Dam Portion 33 Rietvalley No. 364



*Figure 1: Photo taken standing on the western part of the dam wall facing South East*



*Figure 2: Photo taken standing in the middle of the dam wall facing south east*



*Figure 3: Photo taken standing in the middle dam wall facing south*



*Figure 4: Photo taken standing on the eastern part of the dam wall facing West*



Appendix C: Site Photographs Driefontein Dam Portion 33 Rietvalley No. 364



*Figure 5: Photo taken on the eastern part of the dam wall facing south*



*Figure 6: Photo taken from the far eastern part of the dam wall looking west towards to dam*



*Figure 7: Spill way located on the north eastern part of the dam wall*



*Figure 8: Highly degraded stream leaving Driefontein dam to the north of the dam*