

Figure 1:Pipeline Route 1 Alternative 1 represented by die blue line




Figure 2:Adjustment of the last 205m of Pipeline Route 1 represented in green, as recommended by the specialist to avoid going through the bush which may cause the destabilisation of the river bank by removing vegetation.