

Photo 1: Taken from point 1, looking west towards the jetty and Duiwenhoks River



Photo 2: Taken from point 1, looking at the jetty and Duiwenhoks River



Photo 3: Taken from point 2, looking at the footpath cleared through the reedbed towards the jetty



Photo 4: Taken from point 3, looking north towards the buildings, which are well hidden in the thicket vegetation



Photo 5: Taken from point 4, looking at the footpath through the undergrowth of the thicket vegetation, from the swimming pool area.



Photo 6: Taken from point 5, looking west from the main area towards the pool and deck.



Photo 7: Taken from point 6, looking south from the main area deck over the thicket vegetation towards the Duiwenhoks River.



Photo 8: Taken from point 7, looking at the communal bathroom



Photo 9: Taken from point 8, looking at Bedroom 1.



Photo 10: Taken from point 9, looking at Bedroom 2.



Photo 11: Taken from point 10, looking at Bedroom 3.



Google Earth image showing the photograph locations and directions. (Photographs taken on 06 February 2024)

