



Photo 1: View of old plough lines left behind on proposed site



Photo 2: View of the proposed site indicating sparse vegetation



Photo 3: View of existing excavations that form part of site disturbance



Photo 4: View of the proposed site when looking from south-east to north east

