



Photo 1: Photograph of Culvert C10432 where the proposed installing of a gabion basket will extend existing retaining wall (facing upstream)



Photo 2: Photograph of Culvert C10432 of existing gabion basket (facing downstream)



Photo 3: Photograph of accumulated material to be cleared from chamber of culvert



Photo 4: Photograph of accumulated material to be cleared from chamber of culvert



Photo 5: View of Bridge 0496 showing the Hex River flowing underneath



Photo 6: View of Bridge 0496 showing Pier 1 footing of the bridge for which gabion basket installation is proposed to give protection from further erosion



Photo 7: Close-up view showing labelling of Bridge 0496.



Photo 8: View of Bridge 0496 from the eastern side.